

General Environmental Incident Summary

Incident: 3505 **Date/Time Notice:** 10/14/2014 1105 **DEM Incident No:**
Responsible Party: Minot Air Force Base
Date Incident: 10/13/2014 **Time Incident:** 1230 **Duration:**
County: McHenry **Twp:** 152 **Rng:** 77 **Sec:** 19 **Qtr:** SE NW SW
Lat: 47.96737 **Long:** -100.58090 **Method:** Navigation quality GPS
Location Description: A-1 Launch Control Equipment Building (LCEB) 2.5 miles NW of Balfour, ND.

Submitted By: Danny Kluck **Affiliation:** Employee
Address: 5 CES/CEIE
445 Peacekeeper Place
City: Minot AFB **State:** ND **Zip:** 58705

Received By:

Contact Person: Danny Kluck
5 Bomb Wing
201 Summit Drive
Minot AFB, ND 58705

Distance Nearest Occupied Building: 0 Feet **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 65.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Yes

Cause of Incident:

Hydraulic Pumping Unit (HPU) malfunctioned.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 01 - air

Potential Environmental Impacts:

None

Action Taken or Planned:

Missile maintenance team was dispatched and recovered the spill with absorbent pads.

Wastes Disposal Location: Absorbent pads will be taken to the HAZMART facility at Minot AFB.

Agencies Involved:

Updates

Date: 10/27/2014 ***Status:*** Correspondence

Author: Roberts, Kris

Updated Volume:

Notes:

Contacted AFB environmental contact. Leak was in a building with concrete floor. No chance of contamination escaping the building. Response with absorbents was complete. No on-site inspection necessary.